

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
ANNA DR 150	1997	1997	6"	A.C.	1983	PERMIT 5/8/1997	K-COPPER - NO LEADED FITTINGS	3/4"	5/8/1997						YES			
ANNA DR 155	1998	1994	6"	A.C.	1983	PERMIT 7/1/1994	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/1994						YES			
BAY DR 1005 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	1970 Map	VISUAL	COPPER					YES		
BAY DR 1015 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER					YES		
BAY DR 1041 SOUTH		UNKN	6"	A.C.	1970	Map 2012	K-COPPER - NO LEADED FITTINGS	1"	1970 Map	VISUAL	COPPER					YES		
BAY DR 1041 SOUTH			6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2012	VISUAL						YES		
BAY DR 1044 SOUTH			6"	A.C.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	1"	2012	VISUAL						YES		
BAY DR 1045		1951-1972	6"	A.C.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER					YES		
BAY DR 1047		1940-1970	6"	A.C.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	REPLACED 2012	PEX					YES		
BAY DR 1048 SOUTH	2012	2012	6"	A.C.	1970	Map 2012	K-COPPER - NO LEADED FITTINGS	1"	2012	Map 2012	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employee visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BAY DR 1055 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER						YES	
BAY DR 1065 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER						YES	
BAY DR 1075 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER						YES	
BAY DR 1085 SOUTH		UNKN	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL	COPPER						YES	
BAY DR 1089 SOUTH		UNKN	6"	PVC	2014	PERMIT 5/8/2014	K-COPPER - NO LEADED FITTINGS	1"	5/8/2014 Map	VISUAL / CONTRACTOR	COPPER						YES	
BAY DR 1095		1949	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN							YES		
BAY DR 1099 SOUTH		UNKN	6"	PVC	2014	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1970 Map	VISUAL / CONTRACTOR	COPPER						YES	
BAY DR 1103		1946	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN							YES		
BAY DR 1105	2002	1940	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	CONTRACTOR/ VISUAL	COPPER						YES	
BAY DR 1105 SOUTH		UNKN	6"	PVC	2014	PERMIT 10/14/2014	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BAY DR 1106		1963	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1109		1940	6"	C.I.	1964	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1109 SOUTH			6"	PVC	1946	PERMIT 10/6/2014	K-COPPER - NO LEADED FITTINGS	1"	10/6/2014	CONTRACTOR/ VISUAL	COPPER						YES	
BAY DR 1111		1935	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1113		1950	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1115	2010	1957	6"	C.I.	1964	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1115 SOUTH		UNKN	6"	PVC	2014	PERMIT 5/28/2015	K-COPPER - NO LEADED FITTINGS	1"	5/28/2015	VISUAL	COPPER						YES	
BAY DR 1117		1953	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1117 SOUTH		UNKN	6"	PVC	2014	PERMIT 10/9/2014	K-COPPER - NO LEADED FITTINGS	1"	10/9/2014	VISUAL	COPPER						YES	
BAY DR 1119		2003	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BAY DR 1121	1997	1948	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1121 SOUTH		UNKN	6"	PVC	2014	PERMIT 10/9/2014	K-COPPER - NO LEADED FITTINGS	1"	10/9/2014	VISUAL	COPPER						YES	
BAY DR 1125	2002	1943	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1127	2002	1971	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1129		2004	6"	C.I.	1946	PERMIT 11/11/2003	K-COPPER - NO LEADED FITTINGS	3/4"	11/11/2003	VISUAL	COPPER						YES	
BAY DR 1130		1950	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1131		1880	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1133	1997	1906	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1134		1997	6"	C.I.	1946	PERMIT 6/2/1997	K-COPPER - NO LEADED FITTINGS	3/4"	6/2/1997	VISUAL	COPPER						YES	
BAY DR 1135		1920	6"	C.I.	1946	PERMIT 7/16/2010	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BAY DR 1138		1906/1957	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1139		1993	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1140		1968	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1141	2009	dz	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1142	2002	1990	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1143		1957	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	PEX						YES	
BAY DR 1145		1957	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1146	2002	1972	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BAY DR 1147	2009	2006	6"	C.I.	1946	PERMIT 8/5/2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
BAY DR 1148		1957	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BAY DR 1149	2002	1952	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1150	2002	1950	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
BAY DR 1151	2002	1990	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
BAY DR 1156		UNKN	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1157		1946	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1160		1960	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1161		1955	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1162		1955	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1166	2002	1955	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
BAY DR 1176		2003	6"	C.I.	1946	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BEECH ST 110		2003	8"	PVC	2008	PERMIT 8/1/2003	K-COPPER - NO LEADED FITTINGS	2"	8/11/2009	SITE PLANS	COPPER						YES	
BEECH ST 220		1975	4"	C.I.	1961	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
BEECH ST 505		1972	6"	A.C.	1961	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BEECH ST 511		1972	6"	A.C.	1961	UNKN	K-COPPER - NO LEADED FITTINGS	3/14"	UNKN	VISUAL	COPPER						YES	
BEECH ST 520	2009	pre 1954	6"	A.C.	1961	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BEECH ST 521		1952	6"	A.C.	1961	PERMIT 10/11/2006	K-COPPER - NO LEADED FITTINGS	3/4"	10/11/2006	VISUAL	COPPER						YES	
BEECH ST 608		1970	6"	A.C.	1961	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BEECH ST 609		1955	6"	A.C.	1961	PERMIT 11/7/2012	K-COPPER - NO LEADED FITTINGS	3/4"	11/7/2012	VISUAL	COPPER						YES	
BEECH ST 616	2012	1953	6"	A.C.	1961	PERMIT 11/7/2012	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP	VISUAL	COPPER						YES	
BEECH ST 619	2012	1950	6"	A.C.	1961	PERMIT 11/3/2012	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
BEECH ST 716		1966	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP	VISUAL	COPPER						YES	
BEECH ST 718		1972	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BEECH ST 720		1940	6"	A.C.	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 115		1954	12"	PVC	2011	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 116		1955	12"	PVC	2011	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 329		pre 1979	6"	A.C.	1977	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 403	2013	pre 1978	6"	A.C.	1977	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 404		pre 1951	6"	A.C.	1977	NONE	NONE	NONE	UNKN	NONE	NONE							NONE
BIRCH ST 416		pre 1965	6"	A.C.	1977	REPLACED 2017	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
BIRCH ST 419		pre 1978	6"	A.C.	1977	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
CEDAR - VCANT LOT - CORNER OF CEDAR AND OAK Block 8 LOT # 8		NONE	12"	A.C.	1976	NONE	K-COPPER - NO LEADED FITTINGS	1"	1976 MAP									NONE
CEDAR - VCANT LOT - CORNER OF CEDAR AND OAK Block 8 LOT # 7		NONE	12"	A.C.	1976	NONE	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP									NONE
CEDAR ST 701		1965	12"	A.C.	1976	PERMIT 11/2/1997	K-COPPER - NO LEADED FITTINGS	3/4"	11/2/1992	VISUAL	COPPER						YES	
CEDAR ST 703	1998	1982	12"	A.C.	1976	PERMIT 10/13/1981	K-COPPER - NO LEADED FITTINGS	3/4"	10/13/1981	VISUAL	COPPER						YES	
CEDAR ST 707	2002	1952	12"	A.C.	1976	PERMIT 12/3/1984	K-COPPER - NO LEADED FITTINGS	3/4"	12/3/1984	VISUAL	COPPER						YES	
CEDAR ST 711	2006	1947	12"	A.C.	1976	PERMIT 3/31/2006	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP	VISUAL						YES		
CEDAR ST 811	2005	1956	12"	A.C.	1986	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
CEDAR ST 905	2004	1984	12"	A.C.	1976	PERMIT 8/14/2001	K-COPPER - NO LEADED FITTINGS	3/4"	8/14/2001							YES		
CEDAR ST 905	2004	1984	12"	A.C.	1976	2000	K-COPPER - NO LEADED FITTINGS	1"	1976 MAP	VISUAL	COPPER						YES	
CEDAR ST 905		2000	12"	A.C.	1976	PERMIT 9/25/1989	K-COPPER - NO LEADED FITTINGS	6"	1976 MAP	EMPLOYEE KNOWLEDGE	PVC						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
COURT ST 103	2011	1974		C.I.	1935	PERMIT 8/10/1983	K-COPPER - NO LEADED FITTINGS	3/4"	8/10/1983	VISUAL	COPPER						YES	
COURT ST 104		UNKN		C.I.	1335	REPLACED 4/21/2019	PEX	3/4"	5/1/2019	VISUAL	GALVINIZED						YES	
COURT ST 204		pre 1969	8"	C-900	1999	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
COURT ST 220	1998	pre 1971	8"	PVC	1999	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
COURT ST 310		pre 1966	8"	PVC	1999	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
COURT ST 404		1994	8"	PVC	1999	DATA FOR INSTALLATION	K-COPPER - NO LEADED FITTINGS	3/4"	6/9/1989	PERMIT & EMPLOYEES Knowledge	COPPER						YES	
CROCKER BLVD 1151		1961	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
CROCKER BLVD 1163		1960	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
CROCKER BLVD 1169		1960	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
CROCKER BLVD 1175		1988	6"	AC	1955	PERMIT 10/7/1988	K-COPPER - NO LEADED FITTINGS	3/4"	10/7/1988	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
CROCKER BLVD 1195	2002	1948	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
EIGHTH AVE 106		2004	4"	AC	1951	PERMIT 6/30/2003	K-COPPER - NO LEADED FITTINGS	3/4"	6/30/2003	VISUAL	COPPER					YES		
EIGHTH AVE 107	1999	1960	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
EIGHTH AVE 110	2000	1999	4"	AC	1951	PERMIT 10/6/1999	K-COPPER - NO LEADED FITTINGS	3/4"	10/6/1999						YES			
EIGHTH AVE 111	1999	1983	4"	AC	1951	PERMIT 10/20/1983	K-COPPER - NO LEADED FITTINGS	3/4"	10/20/1983	VISUAL						YES		
EIGHTH AVE 205		1985	4"	AC	1951	PERMIT 8/8/1985	K-COPPER - NO LEADED FITTINGS	3/4"	8/8/1985	VISUAL	COPPER					YES		
EIGHTH AVE 206		pre 1960	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
EIGHTH AVE 207		1985	4"	AC	1951	PERMIT 2/15/1984	K-COPPER - NO LEADED FITTINGS	3/4"	2/15/1984	VISUAL	COPPER					YES		
EIGHTH AVE 211		1975	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
EIGHTH AVE 212		pre 1968	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
EIGHTH AVE 217	2002	1975	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
EIGHTH AVE 218		1958	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
EIGHTH AVE 224		pre 1967	4"	AC	1951	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
EIGHTH AVE 317		1983	10"	AC	1976	PERMIT 6/30/1986	K-COPPER - NO LEADED FITTINGS	3/4"	6/30/1986	VISUAL	COPPER						YES	
EIGHTH AVE 318	1999	1890	10"	AC	1976	PERMIT 11/18/1983	K-COPPER - NO LEADED FITTINGS	3/4"	11/18/1983	VISUAL	COPPER						YES	
EIGHTH AVE 320		UNKN	10"	AC	1976	PERMIT 11/1983	K-COPPER - NO LEADED FITTINGS	3/4"	11/28/1983	VISUAL	COPPER						YES	
EIGHTH AVE 414		2010	10"	AC	1976	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
EIGHTH AVE 423		UNKN	10"	AC	1976	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 111	2002	1963	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 120		1910	6"	AC	1963	PERMIT 9/18/1982	K-COPPER - NO LEADED FITTINGS	3/4"	9/8/1982	VISUAL					YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
ELEVENTH AVE 121	1998	1963	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 125		1973	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE - VACANT LOTS Several)	1998	none				NONE	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 4/11/1998	NONE								NONE
ELEVENTH AVE 131		pre 1953	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 404		1998	6"	PVC	1998	VISUAL PERMIT 11/3/1998 VISUAL	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 4/11/1998	VISUAL							YES	
ELEVENTH AVE 420		2006	6"	PVC	1998	VISUAL PERMIT 10/26/2006	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 4/11/1998	VISUAL							YES	
ELEVENTH AVE 507	2011	1958	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 508	1998	1950	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELEVENTH AVE 510	1998	2001	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
ELEVENTH AVE 545	2002	1989	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 246		1963	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 249		1955	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 250		1950	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
ELMS AVE 253		1970	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 298		pre 1964	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 301	2002	1950	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
ELMS AVE 303	2010	2009	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 446	2002	1974	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 450		1953	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
ELMS AVE 455	2011	1978	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 456		1955	6"	AC	1955	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ELMS AVE 464		1969	6"	AC	1955	PERMIT 4/10/1984	K-COPPER - NO LEADED FITTINGS	3/4"	1984	VISUAL	COPPER						YES	
FIFTH AVE VACANT (100 Block)		None	10"	PVC	2008	REPLACED	K-COPPER - NO LEADED FITTINGS	1"	10/22/2007	REPLACED							YES	
FIFTH AVE (200 Block)		None	10"	PVC	2008	REPLACE 10/19/2007	K-COPPER - NO LEADED FITTINGS	3/4"	2007	REPLACE 10/19/2007							YES	
FIFTH AVE 102 S	2009		10"	PVC	2008	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 2007							YES		
FIFTH AVE 106 S		1971	10"	PVC	2008	REPLACED 10/8/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/8/2007	COPPER						YES	
FIFTH AVE 110	1998	1971	10"	PVC	2008	REPLACED 10/2/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/2/2007	COPPER						YES	
FIFTH AVE 111 S		1983	10"	PVC	2008	REPLACED 10/9/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/9/2007							YES	
FIFTH AVE 115						REPLACED 10/9/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/9/2007	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employee visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIFTH AVE 116 S	1997	pre 1962	10"	PVC	2008	REPLACED 10/3/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/3/2007	COPPER					YES		
FIFTH AVE 118 S		1972	10"	PVC	2008	REPLACED 10/2/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	VISUAL	COPPER					YES		
FIFTH AVE 119 S		1972	10"	PVC	2008	REPLACED 10/10/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/10/2007	COPPER					YES		
FIFTH AVE 122	1997	1972	10"	PVC	2008	REPLACED 10/3/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/3/2007	COPPER					YES		
FIFTH AVE 123	1998	1972	10"	PVC	2008	REPLACED 10/10/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/10/2007	COPPER					YES		
FIFTH AVE 126		UNKN	10"	PVC	2008	REPLACED 10/3/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/3/2007	COPPER					YES		
FIFTH AVE 127		1973	10"	PVC	2008	REPLACED 10/10/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/10/2007	COPPER					YES		
FIFTH AVE 209	2011	1955	10"	PVC	2008	REPLACED 10/17/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/17/2007	COPPER					YES		
FIFTH AVE 210	2008	1938	10"	PVC	2008	REPLACED 10/4/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/4/2007	COPPER					YES		
FIFTH AVE 214	1999	1959	10"	PVC	2008	REPLACED 10/4/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/4/2007	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIFTH AVE 215	1998	pre 1971	10"	PVC	2008	REPLACED 10/17/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/17/2007	COPPER					YES		
FIFTH AVE 216	1999	UNKN	10"	PVC	2008	REPLACED 10/5/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/5/2007	COPPER					YES		
FIFTH AVE 222	1999	UNKN	10"	PVC	2008	REPLACED 10/5/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/5/2007	COPPER					YES		
FIFTH AVE 223	1998	1959	10"	PVC	2008	REPLACED 10/17/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/17/2007	COPPER					YES		
FIFTH AVE 224		pre 1966	10"	PVC	2008	REPLACED 10/16/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/16/2007	COPPER					YES		
FIFTH AVE 304	1999	1940	10"	PVC	2014	2007	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 2007	VISUAL	COPPER					YES		
FIFTH AVE 305		UNKN	10"	PVC	2008	REPLACED 10/23/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/23/2007	COPPER					YES		
FIFTH AVE 309		UNKN	10"	PVC	2008	REPLACED 10/23/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/23/2007	COPPER					YES		
FIFTH AVE 313		1934	10"	PVC	2008	REPLACED 10/23/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	EXISTING 10/23/2007	COPPER					YES		
FIFTH AVE 319	1998	1890	10"	PVC	2008	REPLACED 10/24/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 10/24/2007	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employee visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIFTH AVE 402		1880	10"	PVC	2008	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 2020	COPPER					YES		
FIFTH AVE 407	1999	pre 1986	10"	PVC	2008	REPLACED 10/25/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 10/25/2007	COPPER				YES			
FIFTH AVE 408		1986	10"	A.C.	1980	PERMIT 1/16/1985	K-COPPER - NO LEADED FITTINGS	8"	MAP 2007	VISUAL	C-900					YES		
FIFTH AVE 409	2000	1860	10"	PVC	2008	REPLACED 10/26/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 10/26/2007	COPPER				YES			
FIFTH AVE 410	1999	1890	10"	PVC	2008	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	MAP 2007	COPPER				YES			
FIFTH AVE 411		1950	10"	PVC	2008	REPLACED 10/26/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 10/26/2007	COPPER					YES		
FIFTH AVE 416	1999	pre 1971	10"	PVC	2008	REPLACED 10/25/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007	REPLACED 10/25/2007	COPPER				YES	YES		
FIFTH AVE 418	2002	1850	10"	PVC	2008	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007						YES			
FIFTH AVE 506		pre 1971	8"	A.C.	1986	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 1986	VISUAL	COPPER					YES		
FIFTH AVE 518		1952	8"	A.C.	1986	PERMIT 6/17/1988	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIFTH AVE 524	1998	pre 1978	8"	A.C.	1986	PERMIT 10/3/1986	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986	VISUAL	COPPER						YES	
FIFTH AVE 532	1998	1956	8"	A.C.	1986	PERMIT 3/19/1987	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986	VISUAL	COPPER						YES	
FIFTH AVE 550		2008	8"	A.C.	1986	PERMIT 5/12/1987	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986	VISUAL	COPPER						YES	
FIFTH AVE 606	2010	1969	8"	A.C.	1980	PERMIT 8/17/2010	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986							YES		
FIFTH AVE 630/ NONE		1960	8"	A.C.	1980	PERMIT 6/24/1997	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986		NONE							NONE
FIR ST 810		1934	6"	A.C.	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIR ST 811	2012	1958	6"	A.C.	1980	PERMIT 11/5/2012	K-COPPER - NO LEADED FITTINGS	3/4"	11/5/2012	VISUAL	COPPER						YES	
FIR ST 814		1940	6"	A.C.	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST AVE 100	2000	2000	10"	A.C.	1956	PERMIT 8/5/1999	K-COPPER - NO LEADED FITTINGS	3/4"	8/5/1999							YES		
FIRST AVE 101		1940	4"	C.I.	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST AVE 103	1998	1940	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 104	2009	pre 1971	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 110 N	1998	1987	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 110 S .	2005	pre 1961	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 111	1998	UNKN	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 112	1998	pre 1971	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 116		pre 1964	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 117	1998	1985	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FIRST AVE 120	1998	1905	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST AVE 121	2009	pre 1961	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST AVE 124	2009	pre 1958	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 125		1864	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST AVE 126	1998	pre 1962	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 202	2013	1957	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 206	2002	1960	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 212	1998	1953	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 217	1998	1981	6"	AC	1956	PERMIT 7/29/1980	K-COPPER - NO LEADED FITTINGS	3/4"	7/12/2002							YES		
FIRST AVE 306	1998	1963	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST AVE 400	1997	1986	6"	AC	1956	PERMIT 4/14/1986	K-COPPER - NO LEADED FITTINGS	3/4"	4/14/1986	VISUAL	COPPER						YES	
FIRST AVE 401	1998	1985	6"	AC	1956	PERMIT 4/24/1984	K-COPPER - NO LEADED FITTINGS	3/4"	4/24/1984	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD
FIRST AVE 402	1998	1980	6"	AC	1956	PERMIT 1/17/1980	K-COPPER - NO LEADED FITTINGS	3/4"	1/7/1980						YES		
FIRST AVE 405	2024	1984	6"	AC	1956	PERMIT 9/14/1983	K-COPPER - NO LEADED FITTINGS	3/4"	9/14/1983	VISUAL	COPPER					YES	
FIRST AVE 406	1998		6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES		
FIRST AVE 409		1960	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 420		1974	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 422	1998	1967	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 425		1974	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 506		1971	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 514		1972	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
FIRST AVE 520		1977	6"	AC	1956	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST ST 0115 1/2		1982	4"	C.I.	1940	PERMIT 5/10/2010	K-COPPER - NO LEADED FITTINGS	3/4"	7/6/1982	VISUAL	COPPER						YES	
FIRST ST 0114		1910	4"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0115		pre 1962	4"	C.I.	1940	DISCONNECTED 2010	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN									NONE
FIRST ST 0119 W	1998	pre 1952	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0120		1956	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0134		UNKN	8"	PVC	1990	INSTALLED 2017	K-COPPER - NO LEADED FITTINGS	1"	9/26/2017	VISUAL	COPPER						YES	
FIRST ST 0202	1998	pre 1975	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0206	1998	pre 1971	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0208	1998	1958	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
FIRST ST 0225	1998	1958	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST ST 0226	1998	pre 1964	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
FIRST ST 0304	1998	pre 1964	8"	PVC	2018	UNKN	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	WATER PROJECT 2018	COPPER					YES		
FIRST ST 0308		1940	8"	PVC	2018	REPLACED WATER PROJECT 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	REPLACED 8/17/2018	COPPER					YES		
FIRST ST 0312	1998	pre 1959	8"	PVC	2018	REPLACED WATER PROJECT 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	WATER PROJECT 2018	COPPER					YES		
FIRST ST 0314		1950	8"	PVC	2018	UNKN	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	WATER PROJECT 2018	COPPER					YES		
FIRST ST 0400	1998	1961	8"	PVC	2018	UNKN	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	WATER PROJECT 2018	COPPER					YES		
FIRST ST 0404	1999	1957	8"	PVC	2018	UNKN	K-COPPER - NO LEADED FITTINGS	1"	WATER PROJECT 2018	WATER PROJECT 2018	COPPER					YES		
FIRST ST 0429	1998	1914	10"	PVC	2008	REPLACED 10/16/2007	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 10/16/2007						YES			
FIRST ST 0430 / Vacant Lot			10"	PVC	2008	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 2007		NONE					YES		
FIRST ST 0430		1900	10"	PVC	2008	REPLACED 10/11/2007	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 10/11/2007	VISUAL					YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST ST 0502 W	2000	2000	8"	PVC	2015	PERMIT 7/14/2000	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 10/4/2007							YES		
FIRST ST 0520		UNKN	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
FIRST ST 0602		1908	6"	PVC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	New main 2015	VISUAL	COPPER					YES		
FIRST ST 0627		1959	6"	AC	1953	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FIRST ST 0628		UNKN	6"	AC	1953	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FIRST ST 0702 W		1900	4"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
FIRST ST 0706 W	1998	1943	4"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FIRST ST 0712		1940	4"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	PLUMBER	COPPER & PVC					YES		
FIRST ST 0824		1945	10"	AC	1970	Swr only	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	NONE							YES	
FIRST ST 0825		pre 1959	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FIRST ST 0902		1973	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST ST 0905		1978	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST ST 0906	1999	1976	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST ST 1004		pre 1956	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST ST 1007		1957	6"	AC	1950	PERMIT 1/7/1991	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FIRST ST 1010	1998	1947	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
FIRST ST 1110	1999	1978	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH AVE 100		1977	6"	AC	1972	UNKN	K-COPPER - NO LEADED FITTINGS	2"	5/23/1905	VISUAL	COPPER						YES	
FOURTH AVE 101		1977	6"	AC	1972	UNKN	K-COPPER - NO LEADED FITTINGS	2"	5/23/1905	VISUAL						YES		
FOURTH AVE 202		pre 1969	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	AGREEMENT & PICTURE	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FOURTH AVE 203			8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	VISUAL	COPPER							
FOURTH AVE 207		1945	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018	COPPER & PEX						YES	
FOURTH AVE 210		pre 1973	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	REPLACED 2018	COPPER						YES	
FOURTH AVE 215	1999	1899	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018	COPPER						YES	
FOURTH AVE 216	1999	1886	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018	COPPER						YES	
FOURTH AVE 219		1953	8"	PVC	2018	MAP 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	VISUAL	COPPER						YES	
FOURTH AVE 224	1999	1940	8"	PVC	2018	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018	COPPER						YES	
FOURTH AVE 225	1999	pre 1969	8"	PVC	2018	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018							YES	
FOURTH AVE 229	1998	2003	8"	PVC	2018	PERMIT 7/12/2002 REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1" 1"	WATER MAIN PROJECT 2018	WATER MAIN PROJECT 2018	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FOURTH AVE 301	1997	Demo	8"	PVC	2018	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1"	2018	Cut and Capped							NONE	
FOURTH AVE 310	1999	pre 1969	8"	PVC	2018	WATER MAIN PROJECT 2018	K-COPPER - NO LEADED FITTINGS	1"	MAP 2018	WATER MAIN PROJECT 2018	COPPER					YES		
FOURTH AVE 311	1999	1889	8"	PVC	2018	WATER MAIN PROJECT 2018	K-COPPER - NO LEADED FITTINGS	1"	MAP 2018	WATER MAIN PROJECT 2018	COPPER					YES		
FOURTH AVE 402	2002	1885	8"	PVC	2010	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1"	2018 Water Project						YES			
FOURTH AVE 406		2003	8"	PVC	2010	REPLACED 2018	K-COPPER - NO LEADED FITTINGS	1"	2018 Water Project						YES			
FOURTH ST 0609	2002	1926	2"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FOURTH ST 0611	1997	1930	2"	C.I.	1940	PERMIT 7/9/1980	K-COPPER - NO LEADED FITTINGS	3/4"	7/9/1980	VISUAL	COPPER					YES		
FOURTH ST 0611	2009	1930	2"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FOURTH ST 0619		1897	6"	PVC	1982	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
FOURTH ST 0711	2012	1962	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FOURTH ST 0712	2002	UNKN	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	No Plumbing at this time 3/2/2023							YES	
FOURTH ST 0716		None	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN									NONE
FOURTH ST 0800 PARK		None	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	EMPLOYEE KNOWLEDGE	COPPER						YES	
FOURTH ST 0805		1900	10"	AC	1976	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 0809	2001	1900	10"	AC	1976	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 0813		1900	10"	AC	1976	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
FOURTH ST 0901		1900	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 0902		1971	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 0907	2002	1940	8"	HDPE	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 0926		1876	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FOURTH ST 1000		pre 1958	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1001		1982	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1010	2002	pre 1966	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1012	1998	1942	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1013		pre 1958	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1106 - ONE LINE 2 METERS		1968	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1107		UNKN	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
FOURTH ST 1114	2002	1930	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
FOURTH ST 1115	2002	1950	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
FOURTH ST 1205	2007	1971	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employee's visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
FOURTH ST 1209		1970	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GERMAN ST 315		1944	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GERMAN ST 316		1958	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GERMAN ST 515		1955	12"	AC	1970	PERMIT 10/28/1985	K-COPPER - NO LEADED FITTINGS	3/4"	10/28/1985	CUT 2006	COPPER							NONE
GERMAN ST 517		1955	10	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GERMAN ST 609	2012	1977	10	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GERMAN ST 629		None	10	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	EMPLOYEE KNOWLEDGE	COPPER							NONE
GERMAN ST 700		1993	410	AC	1970	WATER INSTALLATION INFO	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN		COPPER						YES	
GERMAN ST 716		1992	6"	AC	1960	PERMIT	K-COPPER - NO LEADED FITTINGS	1 1/2	7/27/1992							YES		
GERMAN ST 807		1945	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
GERMAN ST 819		1963	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GROVE AVE 0965	2000	1987	6"	AC	1950	PERMIT 7/1/1986	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/1986	VISUAL						YES		
GROVE AVE 0966		1988	6"	AC	1950	PERMIT 9/9/1988	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1978	VISUAL	COPPER						YES	
GROVE AVE 1155		1995	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GROVE AVE 1160		1960	6"	AC	1950	PERMIT 12/4/1981	K-COPPER - NO LEADED FITTINGS	3/4"	12/4/1981	VISUAL	COPPER						YES	
GROVE AVE 1161		1981	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
GROVE AVE 1165		1981	6"	AC	1950	PERMIT 10/31/1980	K-COPPER - NO LEADED FITTINGS	3/4"	10/31/1980	VISUAL	COPPER						YES	
HAMILTON ST 411	2002	1979	8"	PVC	2009	Replaced 2009 Water Project	K-COPPER - NO LEADED FITTINGS	1"	7/1/1905								YES	
HAMILTON ST 429	1998	1946	8"	PVC	2009	INSTALLATION INFO	PEX	1"	10/1/2017	NEW INSTALL 2017	PEX & COPPER						YES	
HARRIS AVE 0903		2014	8"	AC	1970	PERMIT	K-COPPER - NO LEADED FITTINGS	3/4"	10/30/2014	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
HARRIS AVE 0906		1900	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
HARRIS AVE 0920		1900	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
HARRIS AVE 0927		1920	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
HARRIS AVE 1010	2002	pre 1979	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
HARRIS AVE 1103		1962	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
HARRIS AVE 1110		1890	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
HARRIS AVE 1115		1951	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
HARRIS AVE 1116		1910	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
HARRIS AVE 1199		UNKN	6"	AC	1950	PERMIT 8/5/1985	K-COPPER - NO LEADED FITTINGS	1"	8/9/1985	VISUAL	COPPER					YES		
HARRIS AVE 1201		UNKN	6"	AC	1950	UNKN	C.I. & PVC	6"	2008 NEW LINE	RECORDS	C-900 & CAST IRON				YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)					
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD
HEMLOCK ST 255 #3		1951	6"	AC/PVC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	1.5"	MAP						YES		
HEMLOCK ST 255 Football field		1951	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES		
HEMLOCK ST 325		1972	10"	AC	1970	PERMIT 8/21/1991	K-COPPER - NO LEADED FITTINGS	3/4"	6/13/1905	VISUAL	COPPER					YES	
HEMLOCK ST 508		1974	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER					YES	
HEMLOCK ST 526		2002	10"	PVC	2007	UNKN	NONE	NONE / WELL	UNKN		NONE				YES		
HEMLOCK ST 560		1954/1977	10"	PVC	2007	2016 LINE INSTALLED	PVC	10" & 4"	NEW 4" LINE 1993 (Trailer Park)	VISUAL	COPPER					YES	
HEMLOCK ST 651		1984	12"	PVC	1980	PERMIT 10/20/1987	K-COPPER - NO LEADED FITTINGS	3/4"	6/9/1905	VISUAL						YES	
HEMLOCK ST 661		1984	12"	PVC	1980	PERMIT 3/29/1984	K-COPPER - NO LEADED FITTINGS	1"	MAP 2005	VISUAL	COPPER					YES	
HEMLOCK ST 671		2005	12"	PVC	2006	PERMIT 7/11/2005	K-COPPER - NO LEADED FITTINGS	1"	DEQ PERMIT	VISUAL						YES	
HILLTOP RD 1179		1968	6"	AC	1950	PERMIT 10/9/1989	K-COPPER - NO LEADED FITTINGS	3/4"	6/11/1905	VISUAL	COPPER					YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
INDUSTRIAL AVE 510 / Coating		1988	6"	PVC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN						YES			
INDUSTRIAL AVE 510 / Plating		N/A	6"	AC	1980	PERMIT 11/14/1988	N/A	NONE / WELL	UNKN									NONE
INDUSTRIAL AVE 510 / PLATING		1980	6"	AC	1980	UNKN	PVC	1"	MAP 1955						YES			
INDUSTRIAL AVE 525		pre 1955	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 1955	VISUAL							YES	
INDUSTRIAL AVE 526		1979	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	1"	MAP 1982	VISUAL							YES	
INDUSTRIAL AVE 705	2011	2011	6"	AC	1980	WATER INSTALLATION	K-COPPER - NO LEADED FITTINGS	3/4"	6/21/2011						YES			
LAKE ST 0000 W Flower Circle		1994	6"	HDPE	1999	2015	K-COPPER - NO LEADED FITTINGS	1"	7/1/2009						YES			
LAKE ST 0101 E		1955	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/2009						YES			
LAKE ST 0108 W		pre 1956	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/2009	VISUAL	COPPER						YES	
LAKE ST 0115 E		2018	12"	PVC	2011	PERMIT 3/27/2019	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/2009	NEW INSTALL 2019	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0125 E	2009	pre 1963	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/2009	VISUAL	COPPER						YES	
LAKE ST 0175 W		1958	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/2009	VISUAL	COPPER						YES	
LAKE ST 0201 E	2011	1920	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/1905	VISUAL	COPPER						YES	
LAKE ST 0207 W		1960	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	7/1/1905	VISUAL	COPPER						YES	
LAKE ST 0211 E		1998	12"	PVC	2011	PERMIT 7/3/1990	K-COPPER - NO LEADED FITTINGS	2"	2009	VISUAL	COPPER						YES	
LAKE ST 0211 W SEC	2009	1960	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0215 W		1960	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0220 W		1976	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	2"	2009	VISUAL	COPPER						YES	
LAKE ST 0306 W		1983	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	COPPER						YES	
LAKE ST 0309 E		2016	10"	PVC	2011	PERMIT 10/14/2016	K-COPPER - NO LEADED FITTINGS	1 1/2" & 1"	10/14/2016	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0310 W Unit C			10"	PVC	2011	PERMIT 5/11/2018	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1986	VISUAL	COPPER						YES	
LAKE ST 0310 W (lake effects)		1963	10"	PVC	1987	PERMIT 4/9/1981	K-COPPER - NO LEADED FITTINGS	3/4"	1981	VISUAL	COPPER						YES	
LAKE ST 0311 W		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986								YES	
LAKE ST 0315 W TAP 1		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986								YES	
LAKE ST 0311 W UNIT 10		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 11		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 12		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 14		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 15		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 16		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0311 W UNIT 63		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0311 W UNIT 09		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0405 WTAPA		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0407 WTAPA		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0405 W TAP 2		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL							YES	
LAKE ST 0315 W UNIT 1		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 2		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 3		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 4		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 5		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0315 W UNIT 6		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 7		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0315 W UNIT 8		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 17		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 18		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 19		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 20		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 21		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 22		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0317 W UNIT 23		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0317 W UNIT 24		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	MAP	VISUAL	COPPER						YES	
LAKE ST 0324 W (well)		1993	26"			NONE				NONE								NONE
LAKE ST 0324 W		1993	12"	PVC	2011	PERMIT 4/9/1981	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	4/9/1981	VISUAL	COPPER						YES	
LAKE ST 0401 E		1998	10"	PVC	2011	PERMIT 3/5/1997 WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1 1/2"	3/5/1997	VISUAL	COPPER						YES	
LAKE ST 0401 W UNIT 25		1989	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	10/8/1986	MAP	COPPER						YES	
LAKE ST 0401 W UNIT 26		1989	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	10/8/1986	MAP	COPPER						YES	
LAKE ST 0401 W UNIT 27		1989	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	10/8/1986	MAP	COPPER						YES	
LAKE ST 0401 W UNIT 28		1989	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	10/8/1986	MAP	COPPER						YES	
LAKE ST 0402 E		1996	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0402 W		1958	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	COPPER					YES		
LAKE ST 0403 W UNIT 49		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 50		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 51		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 52		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 53		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 54		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 55		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0403 W UNIT 56		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		
LAKE ST 0405 W UNIT 33		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER					YES		

CITY OF TAWAS CITY

**Information for the Distribution Systems Material Inventory
(Main to the Curb Stop)**

**Information for the Distribution Systems Material Inventory
(Curb Stop to House or Meter)**

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0405 W UNIT 34		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 35		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 36		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 37		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 38		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 39		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0405 W UNIT 40		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0407 W UNIT 41		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0407 W UNIT 42		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0407 W UNIT 43		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0407 W UNIT 44		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0407 W UNIT 45		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0407 W UNIT 46		1987	6"	PVC	1987	PERMIT 10/8/1986	K-COPPER - NO LEADED FITTINGS	2" & 3/4"	1986	MAP	COPPER						YES	
LAKE ST 0408 W		pre 1959	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	COPPER						YES	
LAKE ST 0410 W		1962	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	COPPER						YES	
LAKE ST 0420 W ANNEX		1993	12"	PVC	2011	PERMIT 12/3/1993	K-COPPER - NO LEADED FITTINGS	2"	1993	VISUAL							YES	
LAKE ST 0422 W Court		1969	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3"	2009	VISUAL	COPPER						YES	
LAKE ST 0428 W JAIL		1969	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	2"	2009	VISUAL							YES	
LAKE ST 0429 E SPRK			6"	PVC	1987	WATER PROJECT 2009	C-900	2"	2009	VISUAL	COPPER						YES	
LAKE ST 0429 W - North Bath House		2018	12"	PVC	2011	WATER PROJECT 2009	PVC	1"	2009	VISUAL	PVC						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0429 W - S Bath House		2018	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	PVC						YES	
LAKE ST 0429 W Jail Sprinklers (city owned)		2016	6"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1 1/2"	2009	VISUAL	COPPER						YES	
LAKE ST 0429 W Bruggers Sprinklers		N/A	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1 1/2"	2009	VISUAL	PVC						YES	
LAKE ST 0431 W CONN		pre 1966	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0432 W		1990	12"	PVC	2011	PERMIT 5/18/1989 WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0438 W		pre 1969	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0442 W		pre 1969	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0444 W		1939	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	2009	VISUAL	COPPER						YES	
LAKE ST 0450 W		pre 1969	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0504 W		1960	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL	COPPER						YES	
LAKE ST 0508 W		1990	12"	PVC	2011	PERMIT 8/22/1990	K-COPPER - NO LEADED FITTINGS	3/4"	1990	VISUAL	COPPER						YES	
LAKE ST 0510 W		1990	12"	PVC	2011	PERMIT 9/22/1990	K-COPPER - NO LEADED FITTINGS	3/4"	1990							YES		
LAKE ST 0512 E		1965	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL							YES	
LAKE ST 0530 E	2009	1935	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009	VISUAL							YES	
LAKE ST 0534 W		pre 1959	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	2009							YES		
LAKE ST 0540 W FIRE LINE		2008	12"	PVC	2011	2009 WHEN BUILDING WAS BUILT	K-COPPER - NO LEADED FITTINGS	6" & 3/4"	2009							YES		
LAKE ST 0540 W UNIT 05		2008	12"	PVC	2011	2016	PVC	6" & 3/4"	2016							YES		
LAKE ST 0540 W UNIT 01		2008	12"	PVC	2011	PERMIT 10/31/2016	PVC	6" & 3/4"	2016							YES		
LAKE ST 0540 W UNIT 02		2008	12"	PVC	2011	PVC TO COPPPER	PVC	6" & 3/4"	2009							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0545 W (DEMO)		1871	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	MAP	VISUAL	COPPER							NONE
LAKE ST 0547 W		pre 1968	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	3/4"	MAP		COPPER						YES	
LAKE ST 0549 W		2014	12"	PVC	2011	PERMIT 8/24/2014	K-COPPER - NO LEADED FITTINGS	1"	8/24/2014	VISUAL	COPPER						YES	
LAKE ST 0550 W C H / IRRIGATION	2009	2008	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	7/1/1905							YES		
LAKE ST 0550 W CH	2009	2008	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	5/1/2009	VISUAL	COPPER						YES	
LAKE ST 0550 W Vet Park / IRRIGATION	2009	2009	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1.5"	7/1/1905	VISUAL	PVC						YES	
LAKE ST 0605 E		2005	12"	HDPE	2000	BUILT 2005	K-COPPER - NO LEADED FITTINGS	1.5"	6/27/1905	VISUAL	COPPER						YES	
LAKE ST 0605 E - SPRK		2005	12"	HDPE	2000	BUILT 2005	K-COPPER - NO LEADED FITTINGS	1.50"	6/27/1905	VISUAL	COPPER						YES	
LAKE ST 0609 W		1920	12"	PVC	2011	WATER PROJECT 2009	K-COPPER - NO LEADED FITTINGS	1"	MAP	VISUAL	COPPER						YES	
LAKE ST 0611 E		2018	12"	HDPE	2000	PERMIT 7/30/2018	K-COPPER - NO LEADED FITTINGS	2"	7/30/2018	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0611 E - SPRK		2018	12"	HDPE	2000	PERMIT 11/30/2004	K-COPPER - NO LEADED FITTINGS	2"	11/30/2004	VISUAL	COPPER						YES	
LAKE ST 0615 W		1940	12"	PVC	2011	PERMIT 5/1/2013	K-COPPER - NO LEADED FITTINGS	3/4"	5/1/2013	VISUAL	PEX						YES	
LAKE ST 0616 W		1975	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0619 W	2013	1930	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0620 W		1922	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
LAKE ST 0621 E . GRDN CENTER		2004	10"	HDPE	2000	BUILT 2004	C-900	2"	2004	VISUAL							YES	
LAKE ST 0621 E .		2004	10"	HDPE	2000	BUILT 2004	C-900	6"	2004	VISUAL	COPPER						YES	
LAKE ST 0621 W	2002	1950	12"	PVC	2011	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
LAKE ST 0623 W		1942	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0624 W	2002	1955	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0625 W		pre 1967	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
LAKE ST 0627	2002	1955	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0629 W		2023	6"	C.I.	1935	PERMIT 6/22/2023	K-COPPER - NO LEADED FITTINGS	3/4"	6/22/2023	VISUAL	COPPER						YES	
LAKE ST 0637 W (sprinklers)		2001	6"	C.I.	1935	PERMIT 6/11/2001	PVC	1"	MAP2001	VISUAL	PVC						YES	
LAKE ST 0637 W UNIT 6		2001	6"	C.I.	1935	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4"	5/29/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 1		2001	6"	C.I.	1935	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 10	2009	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 2	2001	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 3		2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 4	2001	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0637 W UNIT 5	2001	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 7	2001	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 8		2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0637 W UNIT 9	2001	2001	6"	C.I.	1935	2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/2001	VISUAL	COPPER						YES	
LAKE ST 0641 W		1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0643 W	1999	1946	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0646 W	1999	1954	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 701 W		1954	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 703 W		1957	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 704 W	2002	1880	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0705 W		2003	6"	C.I.	1935	PERMIT 4/11/1980	K-COPPER - NO LEADED FITTINGS	3/4"	4/11/1980	VISUAL	COPPER						YES	
LAKE ST 0707 W		2013	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0707 E SPRK	2012	2000	10"	HDPE	2000	PERMIT 10/212/2012	K-COPPER - NO LEADED FITTINGS	1"	10/21/2021	VISUAL	COPPER						YES	
LAKE ST 0707 E		2000	10"	HDPE	2000	PERMIT 10/22/2012	K-COPPER - NO LEADED FITTINGS	1"	10/22/2021	VISUAL	COPPER						YES	
LAKE ST 0709 W		2021	10"	HDPE	2000	PERMIT	K-COPPER - NO LEADED FITTINGS	2"	9/20/2021	VISUAL	COPPER						YES	
LAKE ST 0710 W		1932	6"	C.I.	1935	PERMIT 4/29/1980	K-COPPER - NO LEADED FITTINGS	3/4"	4/29/1980	VISUAL	COPPER						YES	
LAKE ST 0716 W		1946	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0730 W		1940	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0800 W	1998	1955	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0802 W		1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0806 W	1999	1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
LAKE ST 0808 W		1940/1994	6"	C.I.	1935	PERMIT 5/12/1994	K-COPPER - NO LEADED FITTINGS	3/4"	5/12/1994	VISUAL							YES	
LAKE ST 0810 W		1935	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 0814 W		UNKN	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0815 W		2017	6"	C.I.	1935	1985 HAVE MAP	K-COPPER - NO LEADED FITTINGS	1"	1985	WORK ORDER 5/3/2017	PVC						YES	
LAKE ST 0816 W		1920	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0820 W		1930	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 0907 W UNIT 09	1999	1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	MAP	VISUAL	COPPER						YES	
LAKE ST 0907 W UNIT 01		1999	6"	C.I.	1940	5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

**Information for the Distribution Systems Material Inventory
(Main to the Curb Stop)**

**Information for the Distribution Systems Material Inventory
(Curb Stop to House or Meter)**

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0907 W UNIT 10		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 03	1999	1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 04		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 05		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 06		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 07		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 08		1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0907 W UNIT 02	1999	1999	6"	C.I.	1940	PERMIT 5/29/2001	K-COPPER - NO LEADED FITTINGS	3/4 "	6/23/2001	VISUAL	COPPER					YES		
LAKE ST 0908 W		1950	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
LAKE ST 0910 W		1950	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0911 W Irrigation		1999	6"	C.I.	1940	PERMIT 7/1/2000	K-COPPER - NO LEADED FITTINGS	1 1/2 "	6/22/2000								NONE	
LAKE ST 0911 W UNIT 1	2000	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/2001	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 2	2000	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/2001	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 4	2000	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/2001	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 5		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/2001	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 6		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1905	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 7		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1905	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 8		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER						YES	
LAKE ST 0911 W UNIT 3		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER						YES	
LAKE ST 0912 W	1997	1995	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	6/21/1999	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 0915 W UNIT 19-1	2009	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 12-3		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 20-2	2009	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 22-4	2009	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 24-6		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 25-7	2000	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 26-8		1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0915 W UNIT 5	2009	1999	6"	C.I.	1940	2001	K-COPPER - NO LEADED FITTINGS	4" & 3/4"	6/21/1999	VISUAL	COPPER					YES		
LAKE ST 0924 W		demo	6"	C.I.	1940	PERMIT 3/18/1983	K-COPPER - NO LEADED FITTINGS	6"	3/18/2021	DISCONNECT 2009	COPPER					YES		
LAKE ST 0939 W		1990	6"	C.I.	1940	PERMIT 3/23/1990	K-COPPER - NO LEADED FITTINGS	1 1/4"	3/23/1990	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE 0939 W DOCKS		1990	6"	C.I.	1940	PERMIT 3/23/1990	K-COPPER - NO LEADED FITTINGS	1 1/4"	3/23/2090	VISUAL	COPPER						YES	
LAKE ST 950 W		2006	8"	AC	1970	PERMIT 5/21/2004	K-COPPER - NO LEADED FITTINGS	3/4"	MAP							YES		
LAKE ST 1005 W UNIT 1		2009	8"	AC	1970	PERMIT 12/18/2006	K-COPPER - NO LEADED FITTINGS	1 1/2"	MAP 2009	VISUAL	COPPER						YES	
LAKE ST 1005 W UNIT 2		2009	8"	AC	1970	PERMIT 12/18/2006	K-COPPER - NO LEADED FITTINGS	1/1/2"	MAP 2009	VISUAL	COPPER						YES	
LAKE ST 1005 W UNIT 3		2009	8"	AC	1970	PERMIT 12/18/2006	K-COPPER - NO LEADED FITTINGS	1"	MAP 2009	VISUAL	COPPER						YES	
LAKE ST 1005 W UNIT 4		2009	8"	AC	1970	PERMIT 12/18/2006	K-COPPER - NO LEADED FITTINGS	1"	MAP 2009	VISUAL	COPPER						YES	
LAKE ST 1005 W UNIT 5		2009	8"	AC	1970	PERMIT 12/18/2006	K-COPPER - NO LEADED FITTINGS	1"	MAP 2009	VISUAL	COPPER						YES	
LAKE ST 1008 W		pre 1978	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1013 W		1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1015 W		1946	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 1020 W		1999	8"	AC	1970	PERMIT 7/9/1998	K-COPPER - NO LEADED FITTINGS	4"	7/9/1998	VISUAL	COPPER						YES	
LAKE ST 1021 W		1995	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1027 W		1940	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	YEAR BLDG WAS BUILT	COPPER						YES	
LAKE ST 1028 W		1953	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1029 W		1950/1965/1981	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1031 W		1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1033 W		1962	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1043 W		1941/1951	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1070 W		2002	8"	AC	1970	PERMIT 5/30/2002	K-COPPER - NO LEADED FITTINGS	1"	5/30/2002	VISUAL	COPPER						YES	
LAKE ST 1086 W		1949/1966	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 1094 W		1968	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4	UNKN						YES			
LAKE ST 1107		1950	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4	UNKN	VISUAL	COPPER					YES		
LAKE ST 1111 W		1949	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
LAKE ST 1113 W		1939	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER				YES			
LAKE ST 1115 W		1954	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER					YES		
LAKE ST 1115 W		1954	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
LAKE ST 1118 W		1978	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
LAKE ST 1119 W cabins		1946	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN						YES			
LAKE ST 1119 W cabins		1978	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN						YES			
LAKE ST 1122 W		1954	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 1123 W		1995	6"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1124 W POOL	2001	1969	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1124 W House		1946	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1124 W Wing		1954	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1131 W		1983	6"	AC	1950	PERMIT 11/8/1989	K-COPPER - NO LEADED FITTINGS	3/4"	11/8/1989	VISUAL	COPPER						YES	
LAKE ST 1134 W House		1930	6"	AC	1950	PERMIT 10/10/1985	K-COPPER - NO LEADED FITTINGS	3/4"	Demo 2023	VISUAL	COPPER						YES	
LAKE ST 1132 W Shop		1985	6"	AC	1950	PERMIT 7/17/2013	K-COPPER - NO LEADED FITTINGS	1	7/17/2013	VISUAL	COPPER						YES	
LAKE ST 1135 W		1955	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1139 W & 1159		1955	6"	AC	1950	UNKN	CAST IRON	2"	REPAIRED 2015	VISUAL	COPPER						YES	
LAKE ST 1140 W		1952	6"	AC	1950	PERMIT 6/27/1995	K-COPPER - NO LEADED FITTINGS	3/4"	5/3/1905							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
LAKE ST 1142 W	1997	1954	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1144 W		pre 1980	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1146 W		1951	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1150 W		1950	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1165 W		1947	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1190 W - Huron Fitness		1992	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
LAKE ST 1175 W		1971	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1193 W		1983	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1199 W		pre 1953	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
LAKE ST 1202 W		UNKN	6"	AC	1950	1998	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MANOR DR 102		1976	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 115		1970	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 116		1971	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 117		1955	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 119	1997	1956	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 125		1975	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 126		1971	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 131		1971	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 134		1976	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MANOR DR 135		1972	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MANOR DR 143		1980	6"	AC	1935	PERMIT 9/23/1980	K-COPPER - NO LEADED FITTINGS	3/4"	9/23/1980	VISUAL	COPPER						YES	
MANOR DR 144		1978	6"	AC	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MAPLE ST 500		1950	12"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MAPLE ST 514		1999	12"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MAPLE ST 516		pre 1955	12"	AC	1970	PERMIT 2/19/1998	K-COPPER - NO LEADED FITTINGS	3/4"	2/19/1998	VISUAL	COPPER						YES	
MAPLE ST 607		1954	12"	AC	1970	PERMIT 11/5/2012	K-COPPER - NO LEADED FITTINGS	3/4"	11/5/2012	VISUAL							YES	
MAPLE ST 607 small house		1954	12"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
MAPLE ST 620	1998	1970	12"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1976 MAP	VISUAL	COPPER						YES	
MAPLE ST 629		1960	12"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN									NONE
MARGO ST 0289		1974	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MARGO ST 0290		1977	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0299		2000	6"	AC	1960	PERMIT 5/16/2000	K-COPPER - NO LEADED FITTINGS	3/4"	5/16/2000	VISUAL	COPPER						YES	
MARGO ST 0300		1968	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0315		1969	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0320		1973	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0330		1973	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0340		1989	6"	AC	1960	PERMIT 12/21/1987	K-COPPER - NO LEADED FITTINGS	3/4"	12/21/1987	VISUAL	COPPER						YES	
MARGO ST 0350		1977	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 0353		1988	6"	AC	1960	PERMIT 11/9/1987	K-COPPER - NO LEADED FITTINGS	3/4"	11/9/1987	VISUAL	COPPER						YES	
MARGO ST 0360		1962	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MARGO ST 0365		1973	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0370		1973	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0380	2002	1960	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0390		1977	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0400		1962	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0401		1969	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0412		1972	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER					YES		
MARGO ST 0426		1969	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER					YES		
MARGO ST 1006		1963	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
MARGO ST 1026	2002	1973	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MARGO ST 1029		1998	8"	AC	1960	PERMIT 11/11/1989	K-COPPER - NO LEADED FITTINGS	3/4"	11/11/1989	VISUAL	COPPER						YES	
MARGO ST 1032		1971	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1054		1967	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1055		1976	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1059		1993	8"	AC	1960	PERMIT 7/9/1983	K-COPPER - NO LEADED FITTINGS	3/4"	7/9/1983	VISUAL	COPPER						YES	
MARGO ST 1065		1995	8"	AC	1960	PERMIT 9/19/1995	K-COPPER - NO LEADED FITTINGS	3/4"	9/19/1995	VISUAL	COPPER						YES	
MARGO ST 1086		1970	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1089		1979	8"	AC	1960	PERMIT 1/19/1989	K-COPPER - NO LEADED FITTINGS	3/4"	1/9/1989	VISUAL	COPPER						YES	
MARGO ST 1090		1973	8"	AC		UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1092		1976	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MARGO ST 1098		1978	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1100		1977	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1106		1990	8"	AC	1960	PERMIT 8/31/1989	K-COPPER - NO LEADED FITTINGS	3/4"	8/31/1989	VISUAL	COPPER						YES	
MARGO ST 1115		1975	8"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1116	2002	1977	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1118		1975	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1121		1979	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1122		1979	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1125		1977	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
MARGO ST 1135	CHECK INTERIOR	1978	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
MURPHY ST 125		pre 1958	6"	C.I.	1960	UNKN	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 2023	VISUAL	PEX					YES		
NANETTE ST 935		1965	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	PVC					YES		
NANETTE ST 936		Demo	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	NONE						NONE	
NANETTE ST 944		1975	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NANETTE ST 945		1973	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NANETTE ST 955	2002	1968	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NANETTE ST 959		1964	6"	AC	1960	PERMIT 7/3/1990	K-COPPER - NO LEADED FITTINGS	3/4"	6/12/1905	VISUAL	COPPER					YES		
NANETTE ST 960		1974	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NANETTE ST 962		1988	6"	AC	1960	PERMIT 8/19/1988	K-COPPER - NO LEADED FITTINGS	3/4"	6/10/1905	VISUAL	COPPER					YES		
NANETTE ST 963		1975	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
NINTH AVE (500 BLOCK)		NONE	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
NINTH AVE 102		1990	10"	AC	1970	PERMIT 10/17/1988	K-COPPER - NO LEADED FITTINGS	3/4"	6/10/1905	VISUAL	COPPER					YES		
NINTH AVE 104		1990	10"	AC	1970	PERMIT 10/17/1989	K-COPPER - NO LEADED FITTINGS	3/4"	6/11/1905	VISUAL	COPPER					YES		
NINTH AVE 105	2001	2000	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
NINTH AVE 106	1999	1987	10"	AC	1970	PERMIT 2/20/1989	K-COPPER - NO LEADED FITTINGS	3/4"	2/20/1989	VISUAL					YES			
NINTH AVE 110		1987	10"	AC	1970	PERMIT 5/11/1987	K-COPPER - NO LEADED FITTINGS	3/4"	6/9/1905	VISUAL	COPPER					YES		
NINTH AVE 118		1959	10"	AC	1970	PERMIT 10/15/1987	K-COPPER - NO LEADED FITTINGS	3/4"	10/15/1987	VISUAL	COPPER					YES		
NINTH AVE 206	2010	2007	10"	AC	1970	PERMIT 4/17/2007	K-COPPER - NO LEADED FITTINGS	3/4"	6/29/1905	VISUAL	COPPER					YES		
NINTH AVE 211		1947	10"	AC	1970	PERMIT 7/28/1980	K-COPPER - NO LEADED FITTINGS	3/4"	6/2/1905	VISUAL	COPPER				YES			
NINTH AVE 213			10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
NINTH AVE 215		1980	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 219			10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 412		pre 1959	10"	AC	1970	PERMIT 6/7/1982	K-COPPER - NO LEADED FITTINGS	1"	6/4/1905	VISUAL	COPPER						YES	
NINTH AVE 501			10"	AC	1970	PERMIT 5/9/1986	K-COPPER - NO LEADED FITTINGS	3/4"	6/8/1905	VISUAL	COPPER						YES	
NINTH AVE 510	2000		10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 511	1999	pre 1956	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
NINTH AVE 512	2000	pre 1955	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 514		1964	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 518		1946	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 527	2000	pre 1961	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
NINTH AVE 612			10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 615		1922	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 620 (1.5")		1984	10"	AC	1970	PERMIT 7/2/1987	K-COPPER - NO LEADED FITTINGS	2"	7/21/1987	VISUAL	COPPER						YES	
NINTH AVE 620 (1")		pre 1975	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER						YES	
NINTH AVE 706		1956	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NORTH ST 109 W		2002	10"	AC	1970	PERMIT 7/30/2001	K-COPPER - NO LEADED FITTINGS	3/4"	6/23/1905	VISUAL	COPPER						YES	
NORTH ST 111 E		1989	10"	AC	1970	PERMIT 5/11/1987	K-COPPER - NO LEADED FITTINGS	3/4"	6/9/1905	VISUAL	COPPER						YES	
NORTH ST 113 W	2003	2002	10"	AC	1970	PERMIT 5/22/2002	K-COPPER - NO LEADED FITTINGS	3/4"	6/24/1905							YES		
NORTH ST 129			6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	DISCONNECT 2014								NONE
NORTH ST 130 E	1998	1940 /1945	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
NORTH ST 202			10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
NORTH ST 208		1976	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NORTH ST 216			10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN	VISUAL	COPPER					YES		
NORTH ST 301			6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
NORTH ST 307	1998	pre 1953	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
NORTH ST 315		1950	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED					YES		
NORTH ST 318		pre 1960	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	YEAR MAIN WAS INSTALLED	VISUAL	COPPER					YES		
NORTH ST 319	2002	1942	6"	AC	1970	PERMIT 10/17/1979	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
NORTH ST 400		1977	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
NORTH ST 401		1949	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
NORTH ST 404	1998	1954	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NORTH ST 411		1918	6"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN		NONE							NONE
NORTH ST 515	2005	2004	10"	AC	1970	PERMIT 6/3/2004	K-COPPER - NO LEADED FITTINGS	1"	2004	VISUAL							YES	
NORTH ST 601	1999	1971	10"	AC	1970	PERMIT 7/22/1993	K-COPPER - NO LEADED FITTINGS	3/4"	7/22/1993						YES			
NORTH ST 625		1971	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NORTH ST 701		1965	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
NORTH ST 749	1998	1955	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
NORTH ST 825		2017	10"	AC	1970	PERMIT 5/31/2018	K-COPPER - NO LEADED FITTINGS	1"	5/31/2018	INSTALLED 2018							YES	
NORTH ST 901		1991	10"	AC	1970	PERMIT 4/19/1989	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
NORTH ST 907 W		1990	6"	AC	1970	PERMIT 10/17/1989	K-COPPER - NO LEADED FITTINGS	3/4"	10/17/1989	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
PLANK RD 211		1990	6"	AC	1950	PERMIT 7/31/1990	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
PLANK RD 224		UNKN	6"	AC	1950	NONE	K-COPPER - NO LEADED FITTINGS	3/4"	WELL		NONE						NONE	
PLANK RD 232		UNKN	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
PLANK RD 242		UNKN	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
PLANK RD 276		UNKN	6"	AC	1950	NONE	K-COPPER - NO LEADED FITTINGS	3/4"	WELL		NONE						NONE	
PLANK RD 278		UNKN	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
PLANK RD 281		UNKN	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
PLANK RD 282		UNKN	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
PLANK RD 313		UNKN	6"	AC	1950	PERMIT 6/24/1988	K-COPPER - NO LEADED FITTINGS	3/4"	6/20/1905	VISUAL	COPPER					YES		
PLANK RD 315		UNKN	6"	AC	1950	UNKN	NONE	NONE	WELL		NONE				YES		NONE	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
RIVER ST 206 S	1998	pre 1973	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 210 S		pre 1956	8"	PVC	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 215 N	1998	1978	10"	PVC	1990	NONE	NONE	NONE	UNKN	VISUAL						YES		
RIVER ST 216 N		1978	10"	PVC	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	NONE							NONE
RIVER ST 216 S		1900	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
RIVER ST 105 N		1940	10"	C-900	1990	PERMIT 7/3/1992	K-COPPER - NO LEADED FITTINGS	3/4"	6/12/1905	VISUAL						YES		
RIVER ST 125 N		UNKN	10"	PVC	1990	PERMIT 7/3/1992	K-COPPER - NO LEADED FITTINGS	3/4"	6/14/1905	VISUAL	COPPER						YES	
RIVER ST 209 S		1980	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 213 S		1970	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 217 S		UNKN	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
RIVER ST 221 S		1942	8"	C-900	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
RIVER ST 309		1969	10"	AC	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 311 N		1967	10"	AC	1990	NONE	NONE	NONE	NONE	NONE	NONE							NONE
RIVER ST 315 N		1936	10"	AC	1990	NONE	NONE	NONE	NONE	NONE	NONE							NONE
RIVER ST 420 N		1980	10"	AC	1990	PERMIT 6/12/1980	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 421		1936	10"	AC	1990	NONE	NONE	NONE	NONE	NONE	NONE							NONE
RIVER ST 427		1971	10"	AC	1990	PERMIT 8/6/1981	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 515 N		1957	6"	AC	1990	NONE	NONE	NONE	NONE	NONE	NONE							NONE
RIVER ST 522	2019	1940	6"	AC	1990	PERMIT 7/14/1995	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 524	2009	1946	6"	AC	1990	PERMIT 6/24/1980	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
RIVER ST 525		1961	6"	AC	1990	PERMIT 7/26/1989	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER ST 539 N		1973	6"	AC	1990	PERMIT 7/26/2002	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
RIVER VIEW CT 201		1968	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
RIVER VIEW CT 202		1969	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
ROBERTA DR 110		1990	6"	AC	1971	PERMIT 10/2/1989	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ROBERTA DR 131		1989	6"	AC	1971	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 132		1966	6"	AC	1971	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
ROBERTA DR 135		1985	6"	AC	1971	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 139		1980	6"	AC	1971	PERMIT 9/9/1980	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 140		1995	6"	AC	1971	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

**Information for the Distribution Systems Material Inventory
(Main to the Curb Stop)**

**Information for the Distribution Systems Material Inventory
(Curb Stop to House or Meter)**

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
ROBERTA DR 145		1984	6"	AC	1971	PERMIT 7/17/1984	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 148	1998	1983	6"	AC	1971	PERMIT 5/2/1983	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 149		1988	6"	AC	1971	PERMIT 11/11/1986	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 150		1985	6"	AC	1971	PERMIT 3/26/1985	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 151		1991	6"	AC	1971	PERMIT 5/24/1989	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
ROBERTA DR 153		1988	6"	AC	1971	PERMIT 6/30/1987	K-COPPER - NO LEADED FITTINGS	3/4"	6/30/1987	VISUAL	COPPER						YES	
ROBERTA DR 154	2010	1989	6"	AC	1971	PERMIT 5/25/1989	K-COPPER - NO LEADED FITTINGS	3/4"	5/25/1989	VISUAL	COPPER						YES	
SECOND AVE 102	1998	1945	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 106	1998	1958	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 109	1997	1880	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SECOND AVE 110	1998	1956	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 114		pre 1968	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 115		pre 1972	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 118	1998	pre 1957	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 119		pre 1965	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	DISCONNECTED 2019							NONE	
SECOND AVE 120		UNKN	6"	C.I.	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	5/1/2019	REPLACED 2019	COPPER					YES		
SECOND AVE 200	1998	1880	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 201	1998	pre 1973	6"	C-900	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	Curb stop Replaced	GALVINIZED					YES		
SECOND AVE 205	1998	1921	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SECOND AVE 206	1998	1957	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SECOND AVE 209	1998	1940	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SECOND AVE 210	1998	1921	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 213		1940	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
SECOND AVE 217		2021	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SECOND AVE 219 House Burned 2007	1998	pre 1961	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 220	1998	pre 1971	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 222	1998	UNKN	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 223	2007	2007	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 224	2002	1946	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND AVE 227		1910	6"	C-900	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SECOND ST 405		UNKN	8"	PVC	2018	PERMIT 6/21/2018	K-COPPER - NO LEADED FITTINGS	1"	6/21/2016							YES		
SECOND ST 410	1999	pre 1967	8"	PVC	2018	UNKN	K-COPPER - NO LEADED FITTINGS	1"	UNKN							YES		
SECOND ST 429		1908	10"	PVC	2014	REPLACED 10/23/2007	K-COPPER - NO LEADED FITTINGS	1"	MAP 2007							YES		
SECOND ST 500		pre 1953	10"	PVC	2014	REPLACED 10/17/2007	K-COPPER - NO LEADED FITTINGS	1"	10/17/2007							YES		
SECOND ST 605	1999	1987	10"	PVC	2014	PERMIT 11/11/1986	K-COPPER - NO LEADED FITTINGS	1"	2020 WATER PROJECT	2020 WATER PROJECT							YES	
SECOND ST 608		1940	10"	PVC	2014	UNKN	K-COPPER - NO LEADED FITTINGS	1"	2020 WATER PROJECT	2020 WATER PROJECT							YES	
SECOND ST 720		1955	4"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SECOND ST 723		1972	10"	PVC	2014	UNKN	K-COPPER - NO LEADED FITTINGS	1"	2020 WATER PROJECT	VISUAL	COPPER						YES	
SECOND ST 727		1935	10"	PVC	2014	UNKN	K-COPPER - NO LEADED FITTINGS	1"	2020 WATER PROJECT	VISUAL	COPPER						YES	
SECOND ST 730		pre 1962	10"	PVC	2014	PERMIT 10/10/1991	K-COPPER - NO LEADED FITTINGS	1"	2020 WATER PROJECT	VISUAL	GALVINIZED						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SECOND ST 800		pre 1966	4"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SECOND ST 825 Ele Sch		1962	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	2"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 104		1992	6"	AC	1963	PERMIT 6/15/1992	K-COPPER - NO LEADED FITTINGS	3/4"	6/15/1992	VISUAL	COPPER						YES	
SEVENTH AVE 105		1984	6"	AC	1963	PERMIT 9/4/1984	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 108		1991	6"	AC	1963	PERMIT 5/7/1980	K-COPPER - NO LEADED FITTINGS	3/4"	5/7/1980	VISUAL	COPPER						YES	
SEVENTH AVE 109		1999	6"	AC	1963	PERMIT 3/9/1998	K-COPPER - NO LEADED FITTINGS	3/4"	3/9/1998	VISUAL	COPPER						YES	
SEVENTH AVE 113		2001	6"	AC	1963	PERMIT 9/12/2001	K-COPPER - NO LEADED FITTINGS	3/4"	9/12/2001	VISUAL	COPPER						YES	
SEVENTH AVE 115		2002	6"	AC	1963	PERMIT 6/19/2002	K-COPPER - NO LEADED FITTINGS	3/4"	6/19/2002	VISUAL	COPPER						YES	
SEVENTH AVE 117	1999	2002	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SEVENTH AVE 118		1979	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SEVENTH AVE 202	1997	pre 1969	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SEVENTH AVE 205		1945	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
SEVENTH AVE 206		1896	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SEVENTH AVE 210	1998	1935	4"	C.I.	1940	PERMIT	K-COPPER - NO LEADED FITTINGS	3/4"	11/11/2021	DISCONNECTED	NONE							NONE
SEVENTH AVE 211		pre 1972	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SEVENTH AVE 219		1920	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SEVENTH AVE 227		pre 1967	4"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SEVENTH AVE 300		pre 1964	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER					YES		
SEVENTH AVE 301		1872	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SEVENTH AVE 306		UNKN	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SEVENTH AVE 307		1950	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 310	2002	1860	6"	AC	1963	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
SEVENTH AVE 312	2001	UNKN	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP								YES	
SEVENTH AVE 313	2000	1940	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
SEVENTH AVE 318		1920	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
SEVENTH AVE 322		1937	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
SEVENTH AVE 324		UNKN	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	MAP	VISUAL	COPPER						YES	
SEVENTH AVE 328	2002	pre 1975	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	Project	VISUAL	GALVINIZED						YES	
SEVENTH AVE 330		1920	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	GALVINIZED						YES	
SEVENTH AVE 412	2002	1900	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SEVENTH AVE 420	2003	2001	6"	AC	1980	PERMIT 7/26/2001	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 428		UNKN	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 511	2000	1950	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SEVENTH AVE 515	2002	1950	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	REPLACED 1/7/2010 (DPW)	VISUAL	COPPER						YES	
SEVENTH AVE 519		1946	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SIXTH AVE 107	1998	1994	6"	PVC	1980	PERMIT 9/23/2019	K-COPPER - NO LEADED FITTINGS	3/4"	9/23/2019							YES		
SIXTH AVE 108		1996	6"	PVC	1980	PERMIT 9/5/1996	K-COPPER - NO LEADED FITTINGS	3/4"	9/5/1936	VISUAL	COPPER						YES	
SIXTH AVE 110		1998	6"	PVC	1980	PERMIT 10/17/1997	K-COPPER - NO LEADED FITTINGS	3/4"	10/17/1997	VISUAL	COPPER						YES	
SIXTH AVE 111		1995	6"	PVC	1980	PERMIT 9/19/1995	K-COPPER - NO LEADED FITTINGS	3/4"	9/19/1995							YES		
SIXTH AVE 114		1998	6"	PVC	1980	PERMIT 7/8/1998	K-COPPER - NO LEADED FITTINGS	3/4"	7/8/1998	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SIXTH AVE 115		1998	6"	PVC	1980	PERMIT 8/19/1998	K-COPPER - NO LEADED FITTINGS	3/4"	8/19/1998						YES			
SIXTH AVE 119	2004	2003	6"	PVC	1980	PERMIT 12/11/2003	K-COPPER - NO LEADED FITTINGS	1	12/11/2003						YES			
SIXTH AVE 120	2000	1999	6"	PVC	1980	PERMIT 10/14/1999	K-COPPER - NO LEADED FITTINGS	3/4"	10/4/1999	VISUAL						YES		
SIXTH AVE 200	1999	1965	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH AVE 210		PRE 1968	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH AVE 201		1966	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH AVE 209		pre 1960	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH AVE 210		pre 1968	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	Service line replace by customer	DPW inspected when installed	COPPER					YES		
SIXTH AVE 215	1999	pre 1965	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH AVE 218	1999	1919	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SIXTH AVE 224		pre 1958	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SIXTH AVE 225	1999	1886	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SIXTH AVE 227	1998	pre 1951	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SIXTH AVE 228	1998	1970	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL						YES		
SIXTH AVE 229		pre 1959	8"	PVC	2015	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
SIXTH AVE 301	1999	pre 1967	8"	PVC	2020	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	REPLACED 2020	REPLACED 2020	COPPER						YES	
SIXTH AVE 313		1937	8"	PVC	2020	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	REPLACED 2020	REPLACED 2020	COPPER						YES	
SIXTH AVE 415		2022	8"	PVC	2020	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 2007	REPLACED 2020	COPPER						YES	
SIXTH AVE 416		1960	8"	PVC	2020	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	7/12/1905	VISUAL	COPPER						YES	
SIXTH AVE 418	2009	1865	8"	PVC	2020	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SIXTH AVE 420	2002	UNKN	8"	PVC	2020	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
SIXTH ST 1005	2002	1970	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SIXTH ST 1007		pre 1978	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL							YES	
SIXTH ST 1045		1982	10"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SPRING ST 120	1998	1983	10"	AC	1970	PERMIT 4/2/1982	K-COPPER - NO LEADED FITTINGS	3/4"	4/2/1982							YES		
SPRING ST 130	1998	1988	10"	AC	1970	PERMIT 5/22/1987	K-COPPER - NO LEADED FITTINGS	3/4"	5/22/1987							YES		
SUNSET CT 114	2011	2011	6"	AC	1956	WATER INSTALLATION 9/27/2011	K-COPPER - NO LEADED FITTINGS	1"	3/27/2011	VISUAL	COPPER						YES	
SUNSET DR 101		1959	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SUNSET DR 102		1972	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SUNSET DR 116		1960	6"	AC	1950	PERMIT 9/4/1985	K-COPPER - NO LEADED FITTINGS	3/4"	9/4/1985	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SUNSET DR 117		1962	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
SUNSET DR 118		1970	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 119		1969	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 120		1959	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL					YES			
SUNSET DR 121		1957	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 129		1970	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 130	2009	1970	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 135		1970	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 136		1990	6"	AC	1950	PERMIT 10/16/1990	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
SUNSET DR 141		1970	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
SUNSET DR 142	2009	1963	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SUNSET DR 145		1971	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
SUNSET DR 150		1964	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 104		1996	6"	AC	1979	PERMIT 9/18/1996	K-COPPER - NO LEADED FITTINGS	3/4"	9/18/1996	VISUAL	COPPER						YES	
TENTH AVE 110	1999	1996	6"	AC	1979	PERMIT 4/24/1996	K-COPPER - NO LEADED FITTINGS	3/4"	4/24/1996	VISUAL	COPPER						YES	
TENTH AVE 117	1999	UNKN	6"	AC	1979	PERMIT 11/10/1989	K-COPPER - NO LEADED FITTINGS	3/4"	11/10/1989	VISUAL	COPPER						YES	
TENTH AVE 118	1999	1931	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 119	2009	1920	6"	AC	1979	PERMIT 6/17/1998	K-COPPER - NO LEADED FITTINGS	3/4"	6/17/1996	VISUAL	COPPER						YES	
TENTH AVE 121	2009	1978	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 122	1998	1970	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
TENTH AVE 127	2010	1969	6"	AC	1979	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 210		2000	6"	PVC	2000	PERMIT 6/26/2000	K-COPPER - NO LEADED FITTINGS	3/4"	6/26/2020	VISUAL	COPPER						YES	
TENTH AVE 320 Soccer		1991	6"	PVC	2000	1991	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
TENTH AVE 405	1999	1998	6"	PVC	1990	PERMIT 12/8/1998	K-COPPER - NO LEADED FITTINGS	3/4"	12/8/1998	VISUAL							YES	
TENTH AVE 406	1998	1997	6"	PVC	1990	PERMIT 11/2/1997	K-COPPER - NO LEADED FITTINGS	3/4"	11/2/1997	VISUAL	COPPER						YES	
TENTH AVE 410	1998	pre 1974	6"	PVC	1990	WATER INSTALLATION 11/4/2020	K-COPPER - NO LEADED FITTINGS	1"	11/1/2020	VISUAL	COPPER						YES	
TENTH AVE 411	2002	1965	6"	PVC	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 413		2021	6"	PVC	1990	INSTALLED 11/1/2020	K-COPPER - NO LEADED FITTINGS	1"	11/1/2020	VISUAL	COPPER						YES	
TENTH AVE 415	2009	UNKN	6"	PVC	1990	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
TENTH AVE 506	2002	pre 1955	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
TENTH AVE 509	2009	1951	8"	PVC	2000	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
THIRD AVE 105		1973	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
THIRD AVE 106	1998	1971	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 108	1998	1971	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 109	2006	2005	8"	AC	1970	PERMIT 4/18/2005	K-COPPER - NO LEADED FITTINGS	1"	4/18/2005							YES		
THIRD AVE 110	1999	1971	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 111	1998	1986	8"	AC	1970	PERMIT 9/29/1986	K-COPPER - NO LEADED FITTINGS	3/4"	9/29/1996							YES		
THIRD AVE 112		1971	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 113	1998	1984	8"	AC	1970	PERMIT 11/9/1983	K-COPPER - NO LEADED FITTINGS	3/4"	11/9/1963							YES		
THIRD AVE 114	1998	1971	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
THIRD AVE 115	2009	1971	8"	AC	1970	PERMIT 6/20/1984	K-COPPER - NO LEADED FITTINGS	3/4"	6/20/1984						YES			
THIRD AVE 202	1998	1915	8"	AC	1970	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 205		pre 1956	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 206	2009	1850	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 210		1951	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 211	1999	1930	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 214	1998	pre 1962	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 215	2001	2001	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 217	1998	UNKN	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES			
THIRD AVE 218		UNKN	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
THIRD AVE 221		pre 1958	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
THIRD AVE 302	1997	1935	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 303	2009	pre 1963	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 306		pre 1970	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 308	1998	1946	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 309		1905	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 315		pre 1956	6"	C.I.	1940	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
THIRD AVE 430	1998	pre 1951	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN							YES		
TIM CT 614		1972	6"	AC	1960	PERMIT 4/21/1983	K-COPPER - NO LEADED FITTINGS	3/4"	4/21/1983	VISUAL	COPPER						YES	
TIM CT 620		1991	6"	AC	1960	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
TWELFTH AVE 403		2020	8"	PVC	197	PERMIT 6/22/2020	K-COPPER - NO LEADED FITTINGS	1"	6/22/2020	INSTALLED 8/2020	COPPER						YES	
TWELFTH AVE 406		1983	8"	AC	1976	PERMIT 7/15/1983	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1976	VISUAL	COPPER						YES	
TWELFTH AVE 407		1950	8"	AC	1970	PERMIT 9/13/1984	K-COPPER - NO LEADED FITTINGS	3/4"	6/6/1984	VISUAL	COPPER						YES	
TWELFTH AVE 419		1915	8"	AC	1970	PERMIT 7/2/1985	K-COPPER - NO LEADED FITTINGS	3/4"	MAP 1976	VISUAL						YES		
TWELFTH AVE 507	2002	1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL	COPPER						YES	
TWELFTH AVE 508	2011	1972	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL						YES		
TWELFTH AVE 517	2000	1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL						YES		
TWELFTH AVE 520	2011	1978	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL	COPPER						YES	
TWELFTH AVE 521	2002	1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL	COPPER						YES	
TWELFTH AVE 526		1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)						
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
TWELFTH AVE 527		1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL	COPPER						YES	
TWELFTH AVE 532		1978	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	DPW LOWERED SERVICE LINE 2/27/2015							YES	
TWELFTH AVE 533		1979	8"	AC	1970	1977 SPECIAL ASSEMENT	K-COPPER - NO LEADED FITTINGS	3/4"	5/30/1905	VISUAL							YES	
VICTORIA LN 400	2000	2000	6"	AC	1970	PERMIT 7/28/2000	K-COPPER - NO LEADED FITTINGS	3/4"	6/22/1905	VISUAL	COPPER						YES	
VICTORIA LN 505		1979	6"	AC	1950	PERMIT 8/14//1997	K-COPPER - NO LEADED FITTINGS	3/4"	6/19/1905	VISUAL	COPPER						YES	
VICTORIA LN 508		1997	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
VICTORIA LN 511		1979	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
VICTORIA LN 529		1960	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
VICTORIA LN 537		1962	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
VICTORIA LN 557		1981	6"	AC	1950	PERMIT 4/20/1980	K-COPPER - NO LEADED FITTINGS	3/4"	4/20/1980	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)					
												ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD
VICTORIA LN 565	2009	1982	6"	AC	1950	PERMIT 5/29/1981	K-COPPER - NO LEADED FITTINGS	1"	5/29/198	VISUAL	COPPER					YES	
VICTORIA LN 620	2009	1979	6"	AC	1950	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
VICTORIA LN 630		1980	6"	AC	1950	PERMIT 10/16/1979	K-COPPER - NO LEADED FITTINGS	3/4"	10/16/1979	VISUAL	COPPER					YES	
WHEELER ST 124		1950	4"	C.I.	1936	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES		
WHEELER ST 127	1997	1997	4"	C.I.	1936	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN						YES		
WHEELER ST 201		1898	4"	C.I.	1999	1999 WATER PROJECT	K-COPPER - NO LEADED FITTINGS	3/4"	1999 WATER PROJECT	VISUAL	GALVINIZED					YES	
WHEELER ST 203	1998	pre 1965	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	1999 WATER PROJECT	VISUAL	COPPER					YES	
WHEELER ST 210		UNKN	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
WHEELER ST 211		1952	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES	
WHEELER 214		NONE	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	HOME DEMOED		NONE					YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
WHEELER ST 215		pre 1956	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
WHEELER ST 216		UNKN	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
WHEELER ST 218		pre 1961	4"	C.I.	1935	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER					YES		
WHITTEMORE ST 116	1997	1956	8"	PVC	2011	REPLACED 2011 WATER PROJECT	K-COPPER - NO LEADED FITTINGS	3/4"	REPLACED 2011 WATER PROJECT						YES			
WHITTEMORE ST 303	2009	UNKN	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2020 Water Project						YES			
WHITTEMORE ST 304	1999	1872	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2020 Water Project						YES			
WHITTEMORE ST 305	2002	pre 1952	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2020 Water Project						YES			
WHITTEMORE ST 326	1999	UNKN	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2020 Water Project						YES			
WHITTEMORE ST 327 Church		1940	8"	PVC	2010	PERMIT	K-COPPER - NO LEADED FITTINGS	3/4"	8/5/1982	VISUAL	COPPER					YES		
WHITTEMORE ST 327 S/O		1982	8"	PVC	2010	PERMIT	NONE	NONE	NONE	NONE	NONE						NONE	

CITY OF TAWAS CITY

**Information for the Distribution Systems Material Inventory
(Main to the Curb Stop)**

**Information for the Distribution Systems Material Inventory
(Curb Stop to House or Meter)**

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	Information for the Distribution Systems Material Inventory (Main to the Curb Stop)					Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)							
						SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
WHITTEMORE ST 400	2009	pre 1964	8"	PVC	2010	REPLACED 2018 WATER PROJECT	K-COPPER - NO LEADED FITTINGS	1"	MAP 2018	REPLACED 2020	COPPER						YES	
WHITTEMORE ST 416		pre 1954	8"	PVC	2010	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	2020	VISUAL							YES	
WHITTEMORE ST 450	1999	1965	8"	PVC	2010	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	2020 Water Project								YES	
WHITTEMORE ST 527	2002	pre 1951	4"	C.I.	1940	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	2020 WATER PROJECT	2020 WATER PROJECT	COPPER						YES	
WHITTEMORE ST 601		pre 1965	6"	AC	1980	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	1"	REPLACED 2020	REPLACED 2020	COPPER						YES	
WHITTEMORE ST 602		1931	6"	AC	1980	Replaced Water Main Project 2020	K-COPPER - NO LEADED FITTINGS	3/4"	REPLACED 2020	REPLACED 2020	COPPER						YES	
WHITTEMORE ST 625	2009	1945	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
WHITTEMORE ST 629		1920	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN	VISUAL	COPPER						YES	
WHITTEMORE ST 630	1998	pre 1970	6"	AC	1980	UNKN	K-COPPER - NO LEADED FITTINGS	3/4"	UNKN								YES	
WOODWARD AVE 210		1966	8"	AC	1960	PERMIT 9/10/1980	K-COPPER - NO LEADED FITTINGS	3/4"	9/10/1980	VISUAL	COPPER						YES	

CITY OF TAWAS CITY

Information for the Distribution Systems Material Inventory (Main to the Curb Stop)

Information for the Distribution Systems Material Inventory (Curb Stop to House or Meter)

CUSTOMER ADDRESS	METER YEAR	YEAR BUILT (Assessors Records)	MAIN SIZE (Taken from Water Maps)	MAIN MATERIAL (Taken from Water Maps)	YEAR MAIN WAS INSTALLED (Taken from Water Maps)	SERVICE LINE PERMIT/ REPLACED (Water / Sewer Applications)	CITY SERVICE LINE MATERIAL (Water/Sewer Permits, Date main installed were also used, employee knowledge)	SERVICE LINE SIZE FROM MAIN TO CURB STOP (Permits, visual checks and employee knowledge was used)	SERVICE FROM MAIN TO CURBSTOP WAS INSTALLED or REPLACED (City Records and Employee knowledge was used)	VALIDATION METHOD FOR CUSTOMER SERVICE LINE MATERIAL (Employees visual of piping from meter to exterior wall of home)	CUSTOMER SERVICE LINE MATERIAL	ANY PORTION CONTAINS LEAD	CONTAINS GALVANIZED PREVIOUSLY CONNECTED TO LEAD	UNKNOWN -LIKELY CONTAINS LEAD	UNKNOWN - LIKELY DOES NOT CONTAIN LEAD	UNKNOWN -MATERIAL(S) UNKNOWN	CONTAINS NEITHER LEAD NOR GALVANIZED PREVIOUSLY CONNECTED TO LEAD	No Service Line
												0	0	0	0	241	768	45
																TOTAL CUSTOMERS		1054
																TOTAL CUSTOMERS WITH WATER		1009